




Commonwealth Edison  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

October 22, 1979

BBS Ltr #79-837

Mr. James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Reportable Occurrence "Update Report" #79-033/03X-1, Docket #050-237 is hereby submitted to your office to supplement Licensee Event Report 79-033/03L-0 concerning the failure of 2C TIP machine to restart. It addresses the fact that the primary containment integrity was not violated because the reactor water temp. was below 212° F and the reactor mode switch was locked in shutdown for re-fueling. This event was reported to you under Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b).

  
B. B. Stephenson  
Station Superintendent  
Dresden Nuclear Power Station

BBS:lbg

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
File/NRC

1707 291

1002  
11/5/79

7911090 513