

POOR ORIGINAL

## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

CONT

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 At 1900 during routine power operation, it was discovered that the triaxial  
013 time-history accelerometer SI-2-MAT, located on the containment ring girder was  
014 improperly mounted. This created an event contrary to Technical Specification  
015 3.3.3.3 and reportable under Section 6.9.2.b. Redundancy NA. No effect upon  
016 plant or general public. This is the first occurrence of this type reported.

017

018

019

017 018 019 020 021 022 023 024 025 026 027 028 029 030 031 032 033 034 035 036 037 038 039 040 041 042 043 044 045 046 047 048 049 050

017 018 019 020 021 022 023 024 025 026 027 028 029 030 031 032 033 034 035 036 037 038 039 040 041 042 043 044 045 046 047 048 049 050

017 018 019 020 021 022 023 024 025 026 027 028 029 030 031 032 033 034 035 036 037 038 039 040 041 042 043 044 045 046 047 048 049 050

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

010 The cause of this event is attributed to personnel error. SI-2-MAT was dis-  
011 covered to be improperly mounted following a previous maintenance activity.  
012 Maintenance restored operability on 30 October 1979. Technical maintenance  
013 personnel have been instructed of proper installation techniques.

014

015

016

017

018

019

020

021

022

023

024

025

026

027

015 016 017 018 019 020 021 022 023 024 025 026 027 028 029 030 031 032 033 034 035 036 037 038 039 040 041 042 043 044 045 046 047 048 049 050

015 016 017 018 019 020 021 022 023 024 025 026 027 028 029 030 031 032 033 034 035 036 037 038 039 040 041 042 043 044 045 046 047 048 049 050

015 016 017 018 019 020 021 022 023 024 025 026 027 028 029 030 031 032 033 034 035 036 037 038 039 040 041 042 043 044 045 046 047 048 049 050

J. Cooper, Jr.

PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

7911090553

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-098/99T-0

Facility: Crystal River Unit #3

Report Date: 31 October 1979

Occurrence Date: 21 October 1979

Identification of Occurrence:

Triaxial time-history accelograph SI-2-MAT inoperable greater than thirty (30) days contrary to Technical Specification 3.3.3.3 and reportable under Section 6.9.2.b.

Conditions Prior to Occurrence:

Mode 1 power operation (100%).

Description of Occurrence:

At 1900, during routine power operation, it was discovered that the triaxial time-history accelograph SI-2-MAT, located on the containment ring girder was improperly mounted following a previous maintenance activity. Further investigation revealed that the accelograph had been remounted on a hold-down nut that resulted in the accelograph being elevated above its mounting base. Maintenance restored operability on 30 October 1979.

Designation of Apparent Cause:

The cause of this event is attributed to personnel error. SI-2-MAT was improperly mounted following a previous maintenance activity.

Analysis of Occurrence:

No effect upon the plant or general public.

Corrective Action:

Technical maintenance personnel have been instructed of proper accelograph installation techniques.

Failure Data:

This is the first occurrence of this type reported.

/rc

1308 132