

7-771

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT, DESCRIPTION AND PROBABLE CONSEQUENCES (10)

safety were not affected by this incident.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

tinuous current saturation of winding so as to keep motor internals free from (cont)

PHONE: 912-367-7781

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

Reportable Occurrence Report No. 50-366/1979-114

Cause Description and Corrective Action (cont)

moisture. Procedures have been reviewed to determine the number of operations during surveillance and time limit of motor operation. Test equipment has been installed in the circuit to monitor future valve cycles in an attempt to identify the problem. A follow-up report will be submitted with the findings of the investigation.

1787 346