

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

5PO 917-926

SUPPLEMENT TO LER #79-052/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

DISCONNECTED, NOT REALIZING THAT N-31 WAS THE IN-SERVICE SOURCE RANGE DETECTOR. FOLLOWING INSTALLATION OF THE HEAT SHRINK TUBING, THE DETECTOR WAS RETURNED TO SERVICE. THE TECHNICIANS WERE VERBALLY REPRIMANDED BY THEIR IMMEDIATE SUPERVISOR WHO ALSO DISCUSSED THE CONSEQUENCES OF THEIR ACTIONS. ADDITIONAL TRAINING WAS HELD WITH ALL MAINTENANCE REPAIR TECHNICIANS DESCRIBING THIS EVENT AND EMPHASIZING THE IMPORTANCE OF FOLLOWING APPROVED PROCEDURES AND THE SAFETY HAZARDS OF WORKING ON ENERGIZED EQUIPMENT.

1784 030