

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
---	---	---	---	---	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

N	J	S	G	S	1
---	---	---	---	---	---

2	0	0	-	0	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---	---	---

3	4	1	1	1	1
---	---	---	---	---	---

4	5
---	---

7 8 9 14 15 25 26 57 CAT 58

CON'T

0	1
---	---

L	6	0	5	0	0	0	2	7	2
---	---	---	---	---	---	---	---	---	---

7	1	2	2	5	7	9
---	---	---	---	---	---	---

8	0	1	2	4	8	0
---	---	---	---	---	---	---

9

7 8 60 61 66 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During startup operations, routine shift operability tests showed the auxiliary

0 3 alarm typewriter which monitors the containment sump level was not operating

0 4 properly. T/S 3.4.6.1 Action Statement was implemented at 0800 hours. The

0 5 typewriter was repaired, tested and returned to service by 0400 hours on 12/26/79.

0 6 This is the second occurrence of this type (79-32).

0 7

0 8

0 9

0	9
---	---

A	D
---	---

 (11)

E

 (12)

G

 (13)

I	N	S	T	R	U
---	---	---	---	---	---

 (14)

Y

 (15)

Z

 (16)
9 10 11 12 13 18 19 20
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
(17) LER NO. REPORT NUMBER (18) 7 (19) 9 (20) (21) 0 (22) 7 (23) 4 (24) (25) 0 (26) 3 (27) L (28) (29) (30) 0 (31) 0 (32) 0
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
A (18) Z (19) Z (20) Z (21) 0 (22) 0 (23) 0 (24) 0 (25) Y (26) N (27) L (28) R (29) 3 (30) 3 (31) 5 (32) 5
33 34 35 36 37 40 41 42 43 44 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this occurrence was traced to failed components in the typewriter

1 1 logic control. Several logic control boards and a timing control board were

1 2 replaced. The typewriter was tested satisfactorily and returned to service.

1 3

1 4

1	5
---	---

C

 (28)

0	0	2
---	---	---

 (29)

N	A
---	---

 (30)

A

 (31)

Operability Check

 (32)
7 8 9 10 12 13 44 45 46 80
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
1 6 Z (33) Z (34) N/A 44 45 80
7 8 9 10 11 12 13 44 45 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) N/A
1 7 0 (37) 0 (38) Z (39) N/A
7 8 9 10 11 12 13 44 45 80
PERSONNEL INJURIES NUMBER DESCRIPTION (41) N/A
1 8 0 (40) 0 (41) Z (42) N/A
7 8 9 10 11 12 13 44 45 80
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43) N/A
1 9 Z (42) N/A
7 8 9 10 11 12 13 44 45 80
PUBLICITY ISSUED DESCRIPTION (45) N/A
2 0 Z (44) N/A
7 8 9 10 11 12 13 44 45 80
NAME OF PREPARER A. W. KappieNRC USE ONLY
PHCNE: (609) 365-7000 Salem Ext. 628

8001290 461