

Detroit
Edison

January 23, 1980
EF2- 47,354

Mr. James C. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Interim Report of 10CFR50.55(e) Item on Reactor Auxiliary Building Reduced Floor Load.


Dear Mr. Keppler:

On December 27, 1979, Detroit Edison's Mr. H.A. Walker, Site Project Quality Assurance Engineer, telephoned Mr. F.J. Jablonski of NRC Region III to report on a reduced floor load in the Reactor Auxiliary Building at the Fermi 2 Site.

The problem results from cut rebar. So far, it has been determined that 12 slabs are affected. Detroit Edison Engineering is presently analyzing the severity of the problem. A final report will be submitted to you by May 23, 1980.

If you have any questions on this matter, please contact our EF2 Site Project Quality Assurance Engineer.

Sincerely,



W.J. Fahrner
Project Manager
Enrico Fermi 2

cc: Mr. John G. Davis, Acting Director
Office of Inspection and Enforcement
Division of Reactor Inspection Commission
U.S. Nuclear Regulatory Commission
Washington D.C. 20555

1867 056

BO19
SE
110

S 8002040 597