

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
01		A		L		J		M		F		1		2		0		0		-		0		0		0		0		0		-		0		0		3		4		1		1		1		1		4						5																																					
LICENSEE CODE														LICENSE NUMBER																LICENSE TYPE										CAT		58																																																			

CON'T

0 1 REPORT SOURCE L 6 0 3 0 0 0 3 4 8 7 1 2 0 6 7 8 8 0 1 0 5 7 9 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | At 1800 on 12/6/78, while reviewing FNP-1-STP-1.0, it was discovered that the T/S
03 | 4.5.2.a.b requirements were not being met. V8132A, V8132B were open as required but
04 | the breakers to the valve operators were not locked open. T/S 4.5.2.a.b requires that
05 | V8132A, V8132B (charging pump discharge header isolation valves) be open with the
06 | breakers to the valve operators locked open if charging pump 1A is inoperable. Charging
07 | pump 1A was removed from service on 12/5/78 for preventive maintenance. At 1815 on
08 | 12/6/78 the T/S 4.5.2.a.b requirements were complied with. The health/safety of the
09 | general public were not affected by this occurrence.

general public were not affected by this occurrence.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE																
0	9	S	F	A	A	Z	Z	Z	Z	Z	Z	Z	Z	Z																
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21																
LIB. RD. REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER				
17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
		7	8			0	9	0		/	0	3	L		0	H	Z	Z	Z	0	0	0	0	N	N	Z	Z	9	9	9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 When charging pump 1A was declared inoperable and again when FNP-1-STP-1.0 was per-
1 1 formed, the T/S 4.5.2.a.b surveillance requirements were not performed. The required
1 2 surveillance was initiated when the incident was discovered. The individuals involved
1 3 were counseled on the importance of insuring that Technical Specifications are reviewed
1 4 for applicable conditional surveillance and LCO's when equipment is removed from ser-
7 8 9 vice.

8 9 VICE.

FACILITY STATUS (1) 5 (E) (28) % POWER (1) 0 0 (29) OTHER STATUS (30) NA

METHOD OF DISCOVERY (B) (31) Review of surveillance test (32)

ACTIVITY CONTENT RELEASED OF RELEASE (1) 6 (Z) (33) (Z) (34) NA AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES NUMBER (1) 7 (0) 0 0 (37) TYPE (Z) (38) DESCRIPTION (39) NA

PERSONNEL INJURIES NUMBER (1) 8 (0) 0 0 (40) DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY TYPE (1) 9 (Z) (42) NA DESCRIPTION (43)

PUBLICITY ISSUED (2) 1 (N) (44) DESCRIPTION (45) NA

7901100212

NRC USE ONLY

NAME OF PREPARER W. G. Hairston, III

PHONE: (205) 899-5156