

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

① ② N C B E ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿

LICENSEE CODE 15 LICENSE NUMBER 25 LICENSE TYPE 30 CAT 58

CONT

REPORT  
SOURCE

① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿

DOCKET NUMBER 68 EVENT DATE 74 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

① ② A Reactor Operator discovered there was no control board indication for Control

① ③ Building emergency air supply fan B. Lack of control power prevented this fan from

① ④ starting. (Technical Specification 3.7.2)

① ⑤

① ⑥

① ⑦

① ⑧

① ⑨

SYSTEM CODE ⑪ CAUSE CODE ⑫ CAUSE SUBCODE ⑬ COMPONENT CODE ⑭ COMP. SUBCODE ⑮ VALVE SUBCODE ⑯

S G B C C K T B R K E Z

① ⑰ LER RO REPORT NUMBER ⑱ EVENT YEAR ⑲ SHUTDOWN METHOD ⑳ HOURS ㉑ ATTACHMENT SUBMITTED ㉒ NRPD-4 FORM SUB. ㉓ PRIME COMP. SUPPLIER ㉔ COMPONENT MANUFACTURER ㉕

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

① ① A limit switch (VA-ZS-915D) lug, which was found grounded to the switch protective

① ② housing, caused the failure. The grounded lug was re-insulated and the fan returned to

① ③ service operating properly. Other Control Building ventilation system (safety related)

① ④ limit switches of the same design will be examined to verify a similar event is not

① ⑤ occurring. This corrective action should prevent similar events from occurring.

① ⑥

FACILITY STATUS ⑧ % POWER ⑨ OTHER STATUS ⑩ METHOD OF DISCOVERY ⑪ DISCOVERY DESCRIPTION ⑫

E ⑬ 0 9 9 ⑭ NA B ⑮ Operator Observation

① ⑦

ACTIVITY CONTENT ⑧ RELEASED OF RELEASE ⑨ AMOUNT OF ACTIVITY ⑩ LOCATION OF RELEASE ⑪

Z ⑬ Z ⑭ NA NA

① ⑧

PERSONNEL EXPOSURES ⑨ NUMBER ⑩ TYPE ⑪ DESCRIPTION ⑫

0 0 0 ⑬ Z ⑭ NA

① ⑨

PERSONNEL INJURIES ⑩ NUMBER ⑪ DESCRIPTION ⑫

0 0 0 ⑬ NA

① ⑩

LOSS OF OR DAMAGE TO FACILITY ⑪ TYPE ⑫ DESCRIPTION ⑬

⑭

① ⑪

PUBLICITY ⑫ ISSUED ⑬ DESCRIPTION ⑭

⑮

NAME OF PREPARER W. M. Tucker for A.C.T.

PHONE 919-457-6701