

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE 01 A R A N O 2 LICENSE NUMBER 000000000000 LICENSE TYPE 41111 CAT 5

CON'T REPORT SOURCE 01 L DOCKET NUMBER 05000368 EVENT DATE 7122878 REPORT DATE 012579

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During Mode 2 operation, 2P7A, Emergency Feedwater Pump A, tripped on

03 overspeed when started for feeding steam generators violating

04 T.S.3.7.1.2. Redundant Emergency Feedwater pump was available. No

05 similar occurrences. Reportable per T.S.6.9.1.9(b).

06

07

08

09 SYSTEM CODE W B CAUSE CODE E CAUSE SUBCODE A COMPONENT CODE I N S T R U COMP SUBCODE C VALVE SUBCODE 2

LER/HO REPORT NUMBER 17 EVENT YEAR 78 SEQUENTIAL REPORT NO. 032 OCCURRENCE CODE 3 REPORT TYPE L REVISION 00

ACTION TAKEN B FUTURE ACTION Z EFFECT ON PLANT Z SHUTDOWN METHOD Z HOURS 0000 ATTACHMENT SUBMITTED N NPSR-4 FORM SUB N PRIME COMP SUPPLIER N COMPONENT MANUFACTURER W 290

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Investigation revealed a damaged lead in speed control unit. Lead was

11 repaired, Emergency Feedwater Pump, 2P7A, restored to service as required

12 by Action Statement T.S.3.7.1.2.

13

14

FACILITY STATUS 15 B % POWER 003 OTHER STATUS 30 METHOD OF DISCOVERY 1A DISCOVERY DESCRIPTION 32

ACTIVITY CONTENT 16 Z RELEASED OF RELEASE 33 Z AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA

PERSONNEL EXPOSURES NUMBER 17 000 TYPE 37 Z DESCRIPTION 39 NA

PERSONNEL INJURIES NUMBER 18 000 DESCRIPTION 41 NA

LOSS OF OR DAMAGE TO FACILITY TYPE 19 Z DESCRIPTION 43 NA

PUBLICITY ISSUED 20 N DESCRIPTION 45 NA

NAME OF PREPARER Chris N. Shive y PHONE 501/968-2519

NRC USE ONLY

7901310052