


## LICENSEE EVENT REPORT

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	V	A	N	A	S	I	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	9					14	15											25	26								57	CAT	58
LICENSEE CODE								LICENSE NUMBER												LICENSE TYPE										

CON'T

REPORT SOURCE 7 8 60 61 68 69 74 75 80

DOCKET NUMBER 0 1 6 0 5 6 0 0 3 3 8 7 0 1 2 6 7 9 8 0 2 2 2 7 9 9

EVENT DATE

REPORT DATE

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During normal operations, fire door S54-9, between Unit 2 emergency switchgear room and cable vault was found to be non functional. The door latch was missing and therefore could not make up with the strike plate. This resulted in the degradation of the control room fire boundary and positive pressure envelope. This event did not jeopardize the health and safety of the general public.

SYSTEM CODE S G 11		CAUSE CODE A 12		CAUSE SUBCODE E 13		COMPONENT CODE Z Z Z Z Z Z 14						COMP. SUBCODE Z 15		VALVE SUBCODE Z 16			
LER/RO REPORT NUMBER 7 9 17		EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 1 1 24 25 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32							
ACTION TAKEN A 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 38 39 40		ATTACHMENT SUBMITTED Y 23 41		NPRD-4 FORM SUB. N 24 42		PRIME COMP. SUPPLIER Z 25 43		COMPONENT MANUFACTURER Z 9 9 9 9 26 44 45 46 47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Latch was removed from door by person or persons unknown. A watch was posted on the

1 1 door and the latch was replaced immediately.

1 2

1 3

1 4

1 5 FACILITY STATUS E 28 0 9 3 29 % POWER OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Observation 32

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z 33 Z 34 NA

2 9 9 10 11 44

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	Z	38	NA	39

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
		NA	

LOSS OF OR DAMAGE TO FACILITY					
TYPE		DESCRIPTION			
1	9	Z	(42)	NA	(43)
7	8	9	10		8C

PUBLICITY ISSUED (44) DESCRIPTION (45) NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

790 22<sup>0</sup>7 0 403

NAME OF PREPARER W. R. Cartwright

PHONE: 703-894-5151

Description of Event:

On January 26, 1979, during normal operations, S54-9 was discovered not functional in accordance with Technical Specification 3.7.7.1 and 3.7.15. The door was functional in that it was able to close the opening; however, the door latch was missing and therefore the door could not make up with the strike plate establishing a tight seal. This door is in the Unit No. 2 Emergency Switchgear and Relay Room. It shares, however, a common habitability with the Unit No. 1 Switchgear and Relay Room.

Probable Consequences of Occurrence

The Control Room habitability systems required by T.S. 3.7.7.1 and the penetration fire barriers required by T.S. 3.7.15 are provided to assure continuous occupancy of the area during and after natural phenomena, fire and missiles as well as for all postulated accidents which may or may not release radioactivity to the environs. In this case, door S54-9 is used both as a pressure envelope boundary and a penetration fire barrier. The health and safety of operating personnel and the general public were not endangered.

Cause

During construction, the door latch was removed by person or persons unknown.

Immediate Corrective Action

A door watch was stationed to insure complete closure in order to maintain fire and pressure boundaries. A replacement latch was found and immediately installed.

Scheduled Corrective Action

None Required

Actions Taken to Prevent Recurrence

None Required