

PILGRIM NUCLEAR POWER STATION
RFD #1 ROCKY HILL ROAD
PLYMOUTH MASSACHUSETTS 02360

February 14, 1978

- BECo Ltr# 78-22

Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Licensee Event Report 78-04/03L-0

Docket Number 50-293
License DPR-35


Gentlemen:

The attached Licensee Event Report 78-04/03L-0, "Sealant Drift", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B. The Operations Review Committee has reviewed this event and classified it as a condition leading to operation in a degraded mode, Specification 6.9.B.2.6.

A winter snow storm which devastated Massachusetts on February 6, 1978 resulted in many absences at the plant and severely curtailed station administrative activities for the week of February 5 through February 11, 1978. Due to this curtailment this report has been delayed. Every effort is being extended to submit required plant reports on schedule.

If there are any questions on this subject, please contact us.

Respectfully submitted,


P. J. McGuire
Station Manager
Nuclear Operations

CJM:ep

Enclosures: (3 copies)
LER 78-04/03L-0

2259 222

cc: Director (40 copies)
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

A002
5/11

7906040 212