

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 NCBEP2200-00000-00341111145

CON'T
01 REPORT SOURCE L6050-0324711257881227789

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 Remote shutdown drywell temperature recorder CAC-TR-778-1,3,4,7 was not printing and
03 the chart paper was not advancing. This instrument is located on the remote shutdown
04 panel, reactor building 20-foot elevation.

05 (Technical Specification 3.3.5.2)

06
07
08

09 SYSTEM CODE IC11 CAUSE CODE E12 CAUSE SUBCODE B13 COMPONENT CODE INSTRU14 COMP. SUBCODE R15 VALVE SUBCODE Z16

17 LER/RO REPORT NUMBER 78 EVENT YEAR — SEQUENTIAL REPORT NO. 080 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0

ACTION TAKEN B18 FUTURE ACTION Z19 EFFECT ON PLANT Z20 SHUTDOWN METHOD Z21 HOURS 000 ATTACHMENT SUBMITTED N23 NPRO-4 FORM SUB. N24 PRIME COMP. SUPPLIER A25 COMPONENT MANUFACTURER B41526

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 A pin which is used to mechanically connect a rotating shaft to the switching motor
11 gear had sheared and caused the recorder to fail. The recorder was repaired and re-
12 turned to service on 12/6/78. Preventive maintenance is routinely performed on this
13 recorder. This is considered an isolated event and no further corrective action is
14 required.

15 FACILITY STATUS E28 % POWER 09729 OTHER STATUS NA METHOD OF DISCOVERY B31 Routine Inspection

16 ACTIVITY CONTENT Z33 RELEASED OF RELEASE Z34 AMOUNT OF ACTIVITY NA LOCATION OF RELEASE NA

17 PERSONNEL EXPOSURES NUMBER 00037 TYPE Z38 DESCRIPTION NA

18 PERSONNEL INJURIES NUMBER 00040 DESCRIPTION NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z42 DESCRIPTION NA

20 PUBLICITY ISSUED Z44 DESCRIPTION NA

7901030137

NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr.

PHONE (919) 457-6701

GPO 917-926