

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE 01 AIRANO LICENSE NUMBER 00-000000-00 LICENSE TYPE 1111 CAT 58

CON'T REPORT SOURCE L DOCKET NUMBER 050003687 EVENT DATE 123078 REPORT DATE 012979

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During Mode 3 operation, all CEA's fully inserted, signal leads from

03 upper and lower detector chambers of "B" Linear Safety channel NI's

04 were found to be swapped. A failure could have caused a loss of

05 redundancy (i.e. S.A.M. for the affected channel would have been

06 inverted). No similar occurrences. Reportable per T.S.6.9.1.9(c).

07

08

SYSTEM CODE ID CAUSE CODE B CAUSE SUBCODE C COMPONENT CODE I N S T R U COMP. SUBCODE E VALVE SUBCODE Z

LER/NO. REPORT NUMBER 17 EVENT YEAR 78 SEQUENTIAL REPORT NO. 034 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0

ACTION TAKEN B FUTURE ACTION Z EFFECT ON PLANT Z SHUTDOWN METHOD Z HOURS 0000 ATTACHMENT SUBMITTED N NPD-4 FORM SUB N PRIME COMP. SUPPLIER N COMPONENT MANUFACTURER C490

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The Upper and Lower detector chamber leads for the "B" Linear Power

11 Safety Channel NI were reconnected per drawing E-2205, sheet 10 of

12 19. Revision 2.

13

14

FACILITY STATUS B % POWER 0000 OTHER STATUS 30 METHOD OF DISCOVERY A DISCOVERY DESCRIPTION 32

ACTIVITY CONTENT Z AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

PERSONNEL EXPOSURES NUMBER 000 TYPE Z DESCRIPTION 39

PERSONNEL INJURIES NUMBER 000 DESCRIPTION 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z DESCRIPTION 43

PUBLICITY ISSUED N DESCRIPTION 45

NRC USE ONLY

NAME OF PREPARER: Chris N. Shively PHONE: 501/968-2519

790205 0120