

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

1000

2

100

© 2004 Blackwell Publishing Ltd

100

1

1

PHONE: 919-457-6701

LER CONTINUATION -- RO# 1-79-5

Facility: BSEP Unit #1

Event Date 1/4/79

The 1B controller set point adjustment knob locknut was also found missing. Both the 2A & 2B (Unit No. 2) adjustment knob locknuts were examined and found to be installed properly. New locknuts were installed on the 1A & 1B controller knobs. This is considered an isolated event, and no further corrective action is required.