



PILGRIM NUCLEAR POWER STATION
RFD # 1 ROCKY HILL ROAD
PLYMOUTH, MASSACHUSETTS 02360

February 1, 1979

BECO Ltr.#79-72

Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Licensee Event Report 79-001/03L-0

Docket Number 50-293


License DPR-35

Gentlemen:

The attached Licensee Event Report 79-001/03L-0, RBV-PRM Fuse blown, is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B. The Operations Review Committee has reviewed this event and classified it as a condition leading to operation in a degraded mode permitted by a Limiting Condition for Operation (Specification 6.9.B.2.b).

If there are any questions on this subject, please contact us.

Respectfully submitted,


P. J. McGuire
Station Manager
Nuclear Operations

CJM:ep

Enclosures: (3 copies)
LER 79-001/03L-0

cc: Director (40 copies)
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

7902060 280