



Wisconsin Electric POWER COMPANY
231 WEST MICHIGAN, MILWAUKEE, WISCONSIN 53201

DLB

May 21, 1979


Mr. James Keppler, Regional Director
Office of Inspection and Enforcement,
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

DOCKET NOS. 50-266 AND 50-301
POINT BEACH NUCLEAR PLANT
LICENSEE EVENT REPORT NO. 79-008/01T-0

Enclosed is Licensee Event Report No. 79-008/01T-0 (a 14 day followup report) with an attachment in accordance with Technical Specification 15.6.9.2.A.9, "Performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than that assumed in the accident analyses in the safety analysis report or technical specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or correction measures to prevent the existence or development of an unsafe condition."

Very truly yours,



Executive Vice President

Sol Burstein

Enclosures

2274 502

7906060257

22 1979

A002
S
111