

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

500C Chestnut Street Tower II

MAY 31 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - CONTROL LOOP BISTABLES FAIL TO
UNDESIRABLE POSITION ON LOSS OF POWER - NCR MEB 79-10 - REVISED FINAL
REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
Mike Gouge on February 14, 1979. An interim report was submitted on
March 14, 1979, and a final report was sent May 10, 1979.

We have determined that the May 10, 1979, report which stated in the
corrective action section that the wiring to the bistables had been
corrected is in error. The enclosed report contains a revised cor-
rective action section specifying that the wiring diagrams for the
bistables have been corrected, and the physical wiring corrections
for each unit will be completed before its respective fuel load date.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

2337 184

3019
50 1/1

7906080 275

An Equal Opportunity Employer