

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

August 24, 1979

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Failure to Perform SI Pump Test SP1088
Before Leaving Cold Shutdown

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2(c) since it represents an inadequacy in the implementation of administrative controls.

Yours very truly,

David M. Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/jh

cc: Director, IE, USNRC (30)
~~Director~~, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

-over-

2041 198

7908280586

A002
S.11