

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

011 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

011 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

011 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
At 2015 during normal operations RC3, RC6, and RB3 relays tripped in ES Actuation

012 Channel B. This created an event contrary to Technical Specification 3.3.2.1.
013 Maintenance was initiated. There was no effect upon the health or safety of the
014 general public. This is the seventh occurrence concerning ES cabinet relays and
015 the eighteenth event reported under this Specification.
016
017
018

019 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

019 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

019 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

110 The cause is attributed to a failed Hamlin relay. The relay was replaced with a
111 Crydon relay. Post maintenance testing revealed two additional faulty relays.
112 The relays failed as a result of the initial relay failure and were replaced.
113 Operability was restored at 1315 on 3/14/81. A modification will be completed by
114 the next refueling outage to replace Hamlin relays with Crydon relays.

115 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

115 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

115 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

Name of Preparer:

J. J. Buße

PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

8106040340

SUPPLEMENTARY INFORMATION

REPORT NO.: 50-302/81-019/03L-0

FACILITY: Crystal River Unit #3

REPORT DATE: April 10, 1981

OCCURRENCE DATE: 13 March 1981

IDENTIFICATION OF OCCURRENCE: Failure of the Engineered Safety Feature Actuation System Instrumentation Channel contrary to Technical Specification 3.3.2.1.

CONDITIONS PRIOR TO OCCURRENCE: Mode 1 power operation (100%)

DESCRIPTION OF OCCURRENCE: At 2015 during normal operations RC3, RC6 and RB3 relays tripped in ES Actuation Channel B. Emergency safeguards did not actuate. Maintenance was initiated. Operability was restored at 1315 on March 14, 1981 after satisfactory completion of SP-130, Engineered Safeguards Monthly Functional Test.

DESIGNATION OF APPARENT CAUSE: The cause of this event is attributed to a failed Hamlin relay.

ANALYSIS OF OCCURRENCE: There was no effect upon the health or safety of the general public.

CORRECTIVE ACTION: Hamlin relay model 723-12-740 was replaced with a Crydon model A-2410. Post maintenance testing was conducted which indicated additional problems. Further troubleshooting revealed the failure of two (2) additional relays. The relays were replaced and the failure of the relays was considered to be a result of the initial failed relay. A modification package (MAR 80-11-74) has been developed and is being implemented to change from Hamlin relays Model 723-12-740 to Crydon relays Model A-2410 no later than the next refueling outage.

FAILURE DATA: This is the seventh occurrence concerning ES cabinet relays and the eighteenth event reported under this Specification.