

50.55 (e)  
DmB



KANSAS GAS AND ELECTRIC COMPANY

GLENN L. KOESTER  
VICE PRESIDENT - NUCLEAR

June 22, 1981

Mr. G.L. Madsen, Chief  
Reactor Projects Branch  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



KMLNRC 81-089

Re: Docket No. 50-482

Subj: Potential 50.55(e) Report on Cracked  
Parts in NK DC Switchboard

Dear Mr. Madsen:

On May 21, 1981, Mr. E.W. Creel made a telephone report to Mr. W. Hubacek regarding cracks in bus bar type conductors in the NK system DC switchboard.

The contractor initiated Deficiency Report No. SD6905E and the vendor has subsequently replaced the fusible disconnect parts in DC switchboard NK03. Examination of the other DC switchboards revealed no deficient parts.

We have concluded, therefore, that this matter is not reportable under Regulation 10CFR50.55(e).

If you require any additional information, please contact us.

Yours very truly,

*Glenn L. Koester*

GLK:bb

cc: TVandel, Resident NRC Inspector

1E27  
K  
5/10

8106300570

5