

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH March (revised)DOCKET NO. 50-313UNIT NAME ANO - Unit IDATE 4-27-81COMPLETED BY L. S. BramlettTELEPHONE (501) 968-2519

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
81-01	810102	S	432.8	C	1	None	Z	ZZZZZZ	Refueling
81-02	810318	F	1.72	G	3	None	Z	ZZZZZZ	Operations inadvertantly tested the manual trip switch on the new anticipatory RPS trip module while attempting to reset the modules for startup. The modules were tagged with caution cards until they can be relabeled.
81-03	810319	F	3.05	G	3	None	Z	ZZZZZZ	The turbine tripped during the replacement of a blown indicator bulb in the turbine control circuit. The wrong bulb was inadvertantly used.
81-04	810319	S	.56	B	1	None	Z	ZZZZZZ	The unit was taken off line for the turbine overspeed test.

1
F. Forced
S. Scheduled

2
Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

3
Method:
1-Manual
2-Manual Scram.
3-Automatic Scram.
4-Other (Explain)

4
Exhibit G - Instructions
for Preparation of Data
Entry Sheets for Licensee
Event Report (LER) File (NUREG-
0161)

5
Exhibit I - Same Source

(9/77)

8105080 284

8105120284

POOR ORIGINAL