

UPDATE REPORT - PREVIOUS REPORT DATE 3/25/81
LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	B	R	F	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9						14	15	25										26	30					57	CAT	58	
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE									

CON'T

REPORT SOURCE 60 61 0 5 0 0 0 2 6 0 68 69 7 0 3 0 6 8 1 74 75 8 0 4 0 9 8 1 80 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, SI 4.1.B-2 (APRM output signal calibration) was not
0 3 | performed as scheduled. The SI should have been performed between 2/4/81 and
0 4 | 2/6/81. It was performed on 1/29/81, 2/2/81, and 2/11/81. Redundant systems are
0 5 | not applicable. There was no effect on the health or safety of the public.
0 6 | There have been no previous occurrences.
0 7 |
0 8 |

09		SYSTEM CODE Z Z		CAUSE CODE A		CAUSE SUBCODE C		COMPONENT CODE Z Z Z Z Z Z					COMP. SUBCODE Z		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	
LER/RO REPORT NUMBER		EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 1 0		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 1		ACTION TAKEN H		FUTURE ACTION Z		
17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	
EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER Z		COMPONENT MANUFACTURER Z 9 9 9				
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The problem was caused by personnel error. The personnel were cautioned to perform

1 1 SI's as scheduled. No further recurrence control action is planned.

1 2

1 3

1 4

8		9		FACILITY STATUS		% POWER		OTHER STATUS		DISCOVERY METHOD		DISCOVERY DESCRIPTION	
1	5	E	28	0	9	8	29	NA	A	31	During the review cycle		
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE							
1	6	Z	33	Z	34	NA	35	NA	36				
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION							
1	7	0	0	0	37	Z	38	NA	39				
PERSONNEL INJURIES		NUMBER		DESCRIPTION									
1	8	0	0	0	40	NA	41						
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION									
1	9	Z	42	NA	43								
PUBLICITY		ISSUED		DESCRIPTION								NRC USE ONLY	
2	0	N	44	NA	45								

LER SUPPLEMENTAL INFORMATION

BFRC-50- 260 / 8110 Technical Specification Involved 4.1.B

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 3/6/81 Time of Occurrence NA Unit 2

Identification and Description of Occurrence:

SI 4.1.B.2 (APRM Output Signal Calibration) was not performed as scheduled.

Conditions Prior to Occurrence:

Unit 1 at 99% power.

Unit 2 at 98% power.

Unit 3 at 95% power.

Action specified in the Technical Specification Surveillance Requirements met
due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Personnel error.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity,
no damage to plant or equipment and no resulting significant chain of events.

Corrective Action:

Personnel cautioned.

Failure Data:

None

*Retention: Period - Lifetime, Responsibility - Administrative Supervisor

*Revision: 