

DMB/LER



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

July 16, 1981



Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Reactor Water Cleanup Regenerative Heat Exchanger
Piping Leaks

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2d, since abnormal degradation of systems designed to contain radioactive material resulting from the fission process occurred.

Thomas H. Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/TMP/bd

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman

IE22
S
1/1

-over-

8107240174 810716
PDR ADOCK 05000263
S PDR

JUL 20 1981