

USNRC
ATLANTA
OFFICE

OFFICIAL COPY

Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461

July 20, 1981

FILE: B09-13516
SERIAL: BSEP/81-1369

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303



BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 and 2

DOCKET NOS. 50-325 and 50-324

LICENSE NOS. DPR-71 and DPR-62

CONFIRMATION FACSIMILE OF AN IMMEDIATELY REPORTABLE EVENT (1-81-57)

Dear Mr. O'Reilly:

This confirms the conversation between Mr. R. M. Poulk, Jr., Regulatory Specialist, and Mr. C. A. Julian of your office at 1610 on July 18, 1981, concerning an immediately reportable event for both units per Technical Specification 6.9.1.8i.

— i —

At 1515 on July 17, 1981, Carolina Power and Light Company was notified by its architect engineer, United Engineers and Constructors, that an apparent violation of Division 1 and Division 2 cable separation criteria existed. While reviewing the wiring diagram for the RCIC System in preparation for a proposed plant modification it was determined that two non-ESS Division 2 cables were intermixed with one ESS Division 1 cable in a controlled logic panel in the Control Room. The deficiency is in the area of control cabinets internal wiring separation for logic wiring associated with the RCIC steam line isolation valves E51-F007 and E51-F008. This problem is currently being reviewed by plant engineering.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/mcg

cc: Mr. R. A. Hartfield
Mr. V. Stello, Jr.

8107310234 810720
PDR ADOCK 05000324
S PDR

IE22
51/0