



June 15, 1981  
L-81-249

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO  
50-389  
Failure to Follow Radiographic Procedure



On March 12, 1981 (L-81-114), Florida Power & Light Company (FPL) submitted an interim deficiency report, pursuant to the requirements of 10 CFR 50.55 (e), after reporting that a QC Inspector failed to follow the established radiographic procedure when interpreting radiographs of safety-related welds. At that time we stated that a final report would be submitted by June 15, 1981. The required repair work has not yet been completed. FPL anticipates closing out this item by July 31, 1981. A final report will be submitted on or before that date.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/lcg/ah

cc: Harold F. Reis, Esquire

IE27  
S/O

8107310336 810615  
PDR ADOCK 05000389  
S PDR