

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L S L S 1 2 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 36

CON'T

01 L 5 0 5 0 0 0 3 3 5 7 0 6 0 5 8 1 3 0 7 0 6 8 1 9

REPORT SOURCE 30 31 DOCKET NUMBER 38 39 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

03 During normal operation, an electrical ground occurred on the "B" 125 V

03 DC Bus. Investigation of the ground revealed that it was in the

04 control circuitry for 1C Auxiliary Feedwater Pump's turbine-driver governor

05 valve. The pump was declared INOPERABLE and removed from service. In

05 accordance with Tech Spec 3.7.1.2 the subject valve's control circuitry

07 was repaired and 1C Auxiliary Feedwater Pump was operationally tested

03 and returned to service in 64 hours.

SYSTEM CODE S H 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE C 15 VALVE SUBCODE Z 16

LER/RO REPORT NUMBER 17 8 1 0 3 1 OCCURRENCE CODE 0 3 REPORT TYPE L 1 REVISION NO. 0

ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 22 NPRO-4 FORM SUB 23 PRIME COMP SUPPLIER A 24 COMPONENT MANUFACTURER W 25 2 9 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A faulty electro-hydraulic actuator for the governor valve had a grounded

11 coil. A spare actuator was installed which did work properly. The 1C

12 Auxiliary Feedwater Pump was operationally tested satisfactorily and

13 returned to service. This is the 11th C AFW Pump LER but the first of

14 this type.

FACILITY STATUS E 26 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION ELECTRICAL GROUND INVESTIGATION 32

ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE NA 38 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PUBLICITY ISSUED N 44 DESCRIPTION NA 45

NAME OF PREPARER Joe E. Moaba PHONE 552-3680