

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION

0 1 N C M G S 1 2 0 0 - 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
L I C E N S E E R C O D E L I C E N S E N U M B E R L I C E N S E T Y P E C A T 5 6

CON'T
0 1
7 8
R E P O R T S O U R C E
50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
D O C K E T N U M B E R E V E N T D A T E R E P O R T D A T E

E V E N T D E S C R I P T I O N A N D P R O B A B L E C O N S E Q U E N C E S
0 2 While in Mode 5, initial fuel loading, the concentration of oxygen and hydrogen
0 3 in the Waste Gas Shutdown tank exceeded the limits set forth in Technical
0 4 Specification 3.11.2.5. This is reportable per Technical Specification
0 5 6.9.1.12(b). Since no radiation and no ignition source was present, the
0 6 health and safety of the public were not affected.
0 7
0 8

0 9
7 8 9
S Y S T E M C O D E C A U S E C O D E C A U S E S U B C O D E C O M P O N E N T C O D E C O M P S U B C O D E V A L V E S U B C O D E
8 9 10 11 12 13 14 15 16 17 18 19 20
M B 11 A 12 B 13 Z Z Z Z Z Z 14 Z 15 Z 16
E V E N T Y E A R S E Q U E N T I A L R E P O R T N O . O C C U R R E N C E C O D E R E P O R T T Y P E R E V I S I O N N O .
21 22 23 24 25 26 27 28 29 30 31 32
8 1 1 0 8 5 0 3 L 0
A C T I O N T A K E N F U T U R E A C T I O N E F F E C T O N P L A N T S H U T D O W N M E T H O D H O U R S A T T A C H M E N T S U B M I T T E D N P R O - 4 F O R M S U B . P R I M E C O M P S U P P L I E R C O M P O N E N T M A N U F A C T U R E R
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
X 18 G 19 Z 20 Z 21 0 0 0 0 Y 22 N 24 Z 25 Z 26 9 9 9 25

C A U S E D E S C R I P T I O N A N D C O R R E C T I V E A C T I O N S
1 0 A concentration of oxygen and hydrogen was brought about inadvertently due to
1 1 personnel error. The concentrations were brought to within acceptable limits
1 2 and a procedural change was enacted to preclude this situation from occurring
1 3 again.
1 4

1 5
7 8 9
F A C I L I T Y S T A T U S % P O W E R O T H E R S T A T U S M E T H O D O F D I S C O V E R Y D I S C O V E R Y D E S C R I P T I O N
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
X 28 0 0 0 29 Mode 5 A 31 Personnel Observation 32
A C T I V I T Y R E L E A S E D C O N T E N T A M O U N T O F A C T I V I T Y L O C A T I O N O F R E L E A S E
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
Z 33 Z 34 NA NA
P E R S O N N E L E X P O S U R E S P E R S O N N E L I N J U R I E S L O S S O F O R D A M A G E T O F A C I L I T Y P U B L I C I T Y
41 42 43 44 45 46 47 48 49 50
0 0 0 0 37 Z 38 NA
0 0 0 0 40 NA
Z 42 NA
N 44 NA
P U B L I C I T Y I S S U E D D E S C R I P T I O N
45 46 47 48 49 50
N 44 NA

N R C U S E O N L Y

NAME OF PREPARER R. W. Ouellette

PHONE: (704) 373-7530

8107310481 810611
PDR ADOCK 05000369
S PDR