

OFFICIAL COPY

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

100-20-51

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 9, 1981

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station
Unit 2
Docket No. 50-370



Dear Mr. O'Reilly:

In my February 29, 1980 letter which transmitted Significant Deficiency Report SD 369-370/80-01 it was stated that any deficient solid state relays found in Unit 2 would be changed out by January 1, 1981. Due to delays in the delivery of the new relays this work is now expected to be completed by hot functional testing.

Very truly yours,

A handwritten signature in cursive script, appearing to read "William O. Parker, Jr.", written over the typed name.

William O. Parker, Jr.

RWO/php

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE27
5/10

8108030120 810709
PDR ADDCK 05000370
S PDR