

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C M G S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 54

CONT

01 REPORT SOURCE 1 8 0 5 1 0 0 0 0 3 6 9 7 0 5 1 0 7 8 1 1 8 0 6 0 6 8 1 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in Mode 6, initial fuel loading, during valve timing tests the reset
03 pushbutton on the 'Pressurizer Safety Injection Train B' was inadvertently
04 depressed instead of the 'Safety Injection Reset Train 1B' button. This is
05 reportable per Technical Specification 6.9.1.13(c). Since the unit was
06 shutdown and no considerable water volume was transferred, the health and
07 safety of the public were not affected.

08
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

09 SYSTEM CAUSE CAUSE COMPONENT COMP. VALVE
CODE CODE SUBCODE CODE SUBCODE SUBCODE
S F A A Z Z Z Z Z Z Z Z Z Z
11 12 13 14 15 16 17 18 19 20
LER/NO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION
REPORT NUMBER 8 1 0 7 8 0 3 L 0
21 22 23 24 25 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN HOURS ATTACHMENT NPRO- PRIME COMPONENT
TAKEN ACTION ON PLANT METHOD 0 1 0 0 0 Y N Z 9 9 9 9
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The wrong pushbutton was depressed unblocking the pressurizer low pressure
11 signal. A different method will be used to reset the valve timing computer
12 program without depressing the safety injection reset switch. A sliding
13 cover will be placed over these pushbuttons.

14
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

15 FACILITY % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
STATUS 0 0 0 0 Mode 6 A Operator Observation
28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
1 6 Z Z NA NA
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

17 PERSONNEL EXPOSURES
NUMBER TYPE DESCRIPTION
0 0 0 Z NA
37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

18 PERSONNEL INJURIES
NUMBER DESCRIPTION
0 0 0 NA
40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

19 LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION
Z NA
42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

20 PUBLICITY
ISSUED DESCRIPTION
N NA
44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
NRC USE ONLY

NAME OF PREPARER R. W. Ouellette

PHONE: (704) 373-7530