

DMB 50.55(e)  
IE HQS File copy



**LOUISIANA  
POWER & LIGHT**


142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

July 22, 1981

D. L. ASWELL  
Vice President-Power Production

W3K-81-0264  
Q-3-A35.07.27  
Q-3-A35.02.01

Mr. K. V. Seyfrit, Director, Region IV  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 27  
"Switchgear Breaker Position Switch Operator Defect"

Reference: LP&L Letter W3K-81-0147 dated April 13, 1981

Dear Mr. Seyfrit:

Louisiana Power & Light Company submitted the Interim Report for Significant Construction Deficiency No. 27 via the above reference. In that report we indicated that corrective action would be accomplished by July 31, 1981.

We are currently awaiting direction/instructions from General Electric concerning the method of repair. This information is anticipated to be received by July 31, 1981.

The final report for Significant Construction Deficiency No. 27 will be submitted by August 31, 1981.

If you have any questions, please let us know.

Very truly yours,

D. L. Aswell

DLA/LLB/grf

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

IE27  
S  
1/0

8108040151 810722  
PDR ADDCK 05000382  
S PDR