

OFFICIAL COPY



July 24, 1981
L-81-317

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit 2
Docket No. 50-389
Linear Indication In Reactor Coolant
Pipe Weld



On June 24, 1981, Florida Power & Light Company (FPL) notified the Region II Office of Inspection and Enforcement, in accordance with the requirements of 10 CFR 50.55(e), of a potential deficiency regarding a linear indication observed in a reactor coolant system piping weld. The weld in question has been repaired. FPL is still reviewing this problem to confirm whether it is a reportable deficiency under the regulations. A final report will be submitted by August 24, 1981.

Very truly yours,

A handwritten signature in cursive script, reading "Robert E. Uhrig".

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/TCG/ah

cc: Director of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555
Harold F. Reis, Esquire

IED7
5
1/0