

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 T N S N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 57 CAT 56

LICENSEE CODE 14 LICENSE NUMBER 25 LICENSE TYPE 30

REPORT SOURCE 1 6 0 5 0 0 0 3 2 7 7 0 2 1 6 8 1 8 0 7 2 7 8 1 9

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On 6-29-81 it was discovered that a pipe hanger, 1-067-ERCW-042-2, had been removed from the 2" ERCW line to the 1A pipe chase cooler but had not been reinstalled. The hanger had been removed to perform a modification to install a spool piece in the line for the ERCW corrosion study. The event is reportable under 6.9.1.13.c of Sequoyah Unit 1 Technical Specifications. There was no effect upon public health or safety.

Previous Occurrences - None.

SYSTEM CODE W E 11		CAUSE CODE A 12		CAUSE SUBCODE C 13		COMPONENT CODE S U P P O R T 14		COMP SUBCODE A 15		VALVE SUBCODE Z 16	
LEAD/REPORT NUMBER 8 1 21		EVENT YEAR 8 1 22		SEQUENTIAL REPORT NO. 0 7 2 24		OCCURRENCE CODE 0 3 28		REPORT TYPE L 30		REVISION NO. 0 32	
ACTION TAKEN A 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 27		ATTACHMENT SUBMITTED N 23	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27		PRIME COMP. SUPPLIER L 25		NFRD & TOWNS U.S. N 24		COMPONENT MANUFACTURER X 9 9 9 44					

1. The cognizant engineer failed to have the hanger reinstalled after completion of the spool piece installation since he did not consider reinstallation of the hanger a priority item. The hanger was reinstalled on 6-30-81. The cognizant engineer has been instructed on the importance of reinstalling all components as soon as possible.

7 8 9
FACILITY STATUS: 1 5 G 31
% POWER: 0 0 0 29
OTHER STATUS: NA
METHOD OF DISCOVERY: B 31
DISCOVERY DESCRIPTION: QA Observation
80

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 2 11 2 11 NA 44

LOCATION OF RELEASE (36)

NA 45 80

PERSONNEL EXPOSURES					
NUMBER			TYPE	DESCRIPTION	
1	7	0	0	(1) Z (38) NA	39

80

PERSON NUMBER		DESCRIPTION	UNIT	DATE	REMARKS
1	5	0 0 0	NA		

TYPE		DESCRIPTION	
		N/A	(4)

108040626 810727
PDR ADOCK 05000327
S

Name of Preparer: Glenn B. Kirk/Mike R. Harding Phone: (615) 842-8317

Name of Preparer: Glenn B. Kirk/Mike R. Harding

Phone: (615) 842-8317