

**CP&L**

Carolina Power & Light Company

USNRC REGION 2  
ATLANTA, GEORGIA

H. B. ROBINSON STEAM ELECTRIC PLANT

Post Office Box 790

Hartsville, South Carolina 29550

JUL 30 1981

AUG 4 A 8:40

Robinson File No: 2-0-4-1-3

Serial:RSEP/81-645

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
LICENSEE EVENT REPORT 81-004, REVISION 1

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit No. 2, the enclosed Licensee Event Report Revision is submitted. The original report, February 13, 1981, described a RCS leak through a primary system sample heat exchanger tube bundle which was in excess of the amount specified in Technical Specification 3.1.5.2. The report indicated that a review of maintenance records for similar sample heat exchangers would be performed in an effort to identify potential generic problems. The results of this review, reported in this revision, have indicated that no generic problems associated with the reported failure exist. This revision contains a complete description of the event. New information is indicated by a vertical bar in the right hand margin. This report, therefore, supercedes and should replace all copies of the original LER.

Very truly yours,

*R. B. Starkey, Jr.*

R. B. Starkey, Jr.  
General Manager

H. B. Robinson S.E. Plant

FMG/tm

Enclosure

cc: R. A. Hartfield (3)  
V. Stello (30)

IE22  
51/1

8108100006 810730  
PDR ADUCK 05000261  
PDR