

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 28, 1981

TELEPHONE AREA 704
373-4083

Mr. J. P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369



Dear Mr. O'Reilly:

In the LER of Reportable Occurrence Report RO-369/81-93 it was incorrectly stated (Items 10 and 32) that discovery of the occurrence was during performance of an integrated leak rate test (ILRT). The method of discovery was actually routine surveillance. Attached is Revision 1 of the LER reflecting this change. The originally submitted attachment to the LER does not contain this error and thus is still applicable. We regret any confusion or inconvenience this may have caused.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr. *By [Signature]*

PBN:krh
Attachment

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Bill Lavalee
Nuclear Safety Analysis Center
Post Office Box 10412
Palo Alto, California 94303

Ms. M. J. Graham
Resident Inspector - NRC
McGuire Nuclear Station

*IE22
6/11*

8108100216 810728
PDR ADOCK 05000369
S PDR