

USNRC REGION II  
ATLANTA, GEORGIAUSNRC REGION II  
ATLANTA, GEORGIA

01 AUG 3 PI2: 15

01 JUL 30 AIO: 56

July 27, 1981  
L-81-321

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit 2  
Docket No. 50-389  
Modutronic Controller/Allen  
Bradley Selector Switches

On June 24, 1981, Florida Power & Light Company (FPL) notified the Region II Office of Inspection and Enforcement of a potential 10CFR50.55(e) deficiency regarding the mounting of Modutronic Controller/Allen Bradley Selector Switches. During fabrication of the boxes containing the control switches, the slot to hold the locking ring was omitted. As a result the locking rings were left off. In this condition the switch housing rotates when the switch is turned which could result in broken, damaged, or shorted connections. FPL is evaluating this deficiency and we expect to provide you additional information by August 3, 1981.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/TCG/bs

cc: Director of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Harold F. Reis, Esquire



IE27  
S/O