


BMB/LER



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901



July 31, 1981

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315
AEU No. 81-024/04X-0

Dear Mr. Keppler:

This report is being submitted as required by Technical Specification 3.3.3.4, as the Meteorological 150 foot wind direction instrumentation was declared inoperable on July 16, 1981, due to erratic operation.

The cause was determined to be a faulty wind direction sensor, manufactured by Geotech-Model No. 50.2C. Due to several previous lightning strikes, the plant was out of spare units and additional units were on order. The back order was expedited.

The 150 foot wind direction indication was repaired and placed in operation on July 29, 1981.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.S. Hunter
R.W. Jurgensen
R.F. Kroeger
K.J. Vehstedt
E. Swanson/N. DuBry RO:III
R.C. Callen MPSC
G. Charnoff, Esq.

J.M. Hennigan
W. Lavallee EPRI
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (20 copies)
Dir., MIPC (2 copies)
Directorate of Licensing

IE22
s
1/0