

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: 01 N J S G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSE NUMBER: 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

REPORT SOURCE: 01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On July 3, 1981, while trying to adjust service water flow through No. 12 component cooling water heat exchanger (CCW Hx), the operator noticed that flow control valve 12SW127 would not open. The valve was declared inoperable, and action statements 3.7.3.1 and 3.5.2.a were entered at 0420 hours, July 3, 1981.

SYSTEM CODE: C J 11 CAUSE CODE: E 12 CAUSE SUBCODE: B 13 COMPONENT CODE: V A L V E X 14 COMP SUBCODE: A 15 VALVE SUBCODE: G 16

EVENT YEAR: 8 1 SEQUENTIAL REPORT NO.: 0 6 9 OCCURRENCE CODE: 0 3 REPORT TYPE: L 17 REVISION NO.: 0 18

LER REPORT NUMBER: 0 1 19 ACTION TAKEN: F 16 20 FUTURE ACTION: A 19 EFFECT ON PLANT: Z 20 SHUTDOWN METHOD: Z 21 HOURS: 0 0 0 0 22 ATTACHMENT SUBMITTED: Y 23 NPD-4 FORM SUB: Y 24 PRIME COMP. SUPPLIER: L 25 COMPONENT MANUFACTURER: F 1 3 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Component failure. The sealing surface of the valve tube bundle was marred, restricting movement. The valve was removed from service, disassembled, and the tube bundle cut back to allow free movement. It was reassembled, tested satisfactorily, and returned to service. Action statements 3.7.3.1 and 3.5.2.a were terminated at 0250 hours, July 4, 1981.

FACILITY STATUS: E 28 % POWER: 0 9 7 29 OTHER STATUS: N/A 30 METHOD OF DISCOVERY: A 31 DISCOVERY DESCRIPTION: Operator Observation 32

ACTIVITY CONTENT: Z 33 Z 34 AMOUNT OF ACTIVITY: N/A 35 LOCATION OF RELEASE: N/A 36

PERSONNEL EXPOSURES: NUMBER: 0 0 0 37 TYPE: Z 38 DESCRIPTION: N/A 39

PERSONNEL INJURIES: NUMBER: 0 0 0 40 DESCRIPTION: N/A 41

LOSS OF OR DAMAGE TO FACILITY: TYPE: Z 42 DESCRIPTION: N/A 43

PUBLICITY: ISSUED: N 44 DESCRIPTION: N/A 45

8108110583 810731
PDR ADDOCK 05000272
S PDR

NRC USE ONLY

NAME OF PREPARER: Frank Dickey PHONE: 609-935-5100