

USNRC REGION II
ATLANTA, GEORGIA

31 AUG 5 AM 11

August 3, 1981
L-81-332

Mr. James P. O'Reilly, Director, Region II
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit 2
Docket No. 50-389
Failure to Follow Radiographic Procedure



On March 12, 1981 (L-81-114), Florida Power & Light Company (FPL) submitted an interim deficiency report, pursuant to the requirements of 10 CFR 50.55(e), after reporting that a QC Inspector failed to follow the established radiographic procedure when interpreting radiographs of safety-related welds. On June 15, 1981 (L-81-249), FPL informed you that a final report would be submitted by July 31, 1981. At this time, twenty-five (25) weld joints still require repair. We now expect to complete this work by October 30, 1981. A final report will be submitted at that time.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/TCG/ah

cc: Harold F. Reis, Esquire

IE27
S/D

8108130148 810803
PDR ADOCK 05000389
S PDR