

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	A	P	P	S	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0	1	L	6	0	5	0	-	0	2	9	3	7	0	7	1	7	8	1	8	0	8	1	4	8	1	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCE (10)

0 2 | During Chemistry Lab calibration of Panel C-19 (Leak Detection Air Sampler) the

0 3 | iodine Radiation Monitor channel was observed to be inoperative. This is contrary

0 4 | to T.S. 3.6.C.2 which limits reactor operation to the succeeding seven days or until

0 5 | system is declared operable. During the time the system was inoperative, the

0 6 | required redundant leak detection systems were operable.

0 7 |

0 8 |

0	9	C	I	11	X	12	X	13	I	N	S	T	R	U	14	E	15	Z	16	17	8	1	0	4	0	0	3	L	0
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	----	---	---	---	---	---	---	---	---	---

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 R 3 6 2 26
33 34 35 36 37 40 41 42 43 44 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | An "A" priority MR (#81-4-38) was issued to determine cause and to correct this

1 1 | failure. In the process of replacing a trending recorder to the iodine channel,

1 2 | a voltage transient occurred causing a transistor to open. The transistor was

1 3 | replaced, the calibration completed and the system declared operative that same

1 4 | day. This is an isolated event.

1	5	E	28	1	0	0	29	N.A.	30	A	31	Calibration	32
---	---	---	----	---	---	---	----	------	----	---	----	-------------	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
1 6 Z 33 Z 34 N.A. N.A.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
1 7 0 0 0 37 Z 38 N.A.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
PERSONNEL INJURIES NUMBER DESCRIPTION
1 8 0 0 0 40 N.A.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
1 9 Z 42 N.A.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
PUBLICITY ISSUED DESCRIPTION
2 0 N 44 N.A.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
8108210424 810814
PDR ADOCK 05000293
S PDR
NRC USE ONLY
NAME OF PREPARER G.G. Whitney PHONE 617-746-7900