



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 8008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366 2345

August 25, 1981

D. L. ASWELL
Vice President-Power Production

W3K81-0300
Q-3-A35.07
Q-3-A35.02.01

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3
Interim Report of Potential Reportable
Incident #49 "Material Properties of
Tube Track and Welded Fittings"



Reference: (1) Telcon, L. L. Bass (LP&L) to B. Hubacek (NRC) on 7/22/81
(2) Telcon, L. L. Bass (LP&L) to B. Hubacek (NRC) on 8/21/81

Dear Mr. Seyfrit:

As discussed in the Reference (2) telecon, the evaluation of the significance of PRI #49 "Material Properties of Tube Track and Welded Fittings" has not been completed at this time. The engineering evaluation of material certificates by Ebasco New York has not been completed. It is estimated that this evaluation will be completed by September 1, 1981.

Based on the above status, a final report will be submitted by September 23, 1981.

Yours very truly,

D. L. Aswell

DLA/LLB/grf

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE27
S
1/0