

LICENSEE EVENT REPORT

CONTROL BLOCK

1	2	3	4	5	6
---	---	---	---	---	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

N	J	S	G	S	2	7	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 52DON'T

0	1
---	---

 REPORT SOURCE

1	6	0	5	0	0	0	3	1	1	7	0	8	1	2	8	1	8	0	9	0	9	8	1	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2
---	---

 On August 12, 1981, during a routine surveillance, it was discovered that 2B1 battery

0	3
---	---

 charger would not pick up the 28-volt d.c. electrical load. At 0420 hours, 2B1

0	4
---	---

 battery charger was declared inoperable, and action statement 3.8.2.5 was entered.

0	5
---	---

0	6
---	---

0	7
---	---

0	8
---	---

0	9
---	---

E	C	11
---	---	----

X	12
---	----

Z	13
---	----

B	A	T	T	R	Y	14
---	---	---	---	---	---	----

Z	15
---	----

Z	16
---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
LER NO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION NO
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPDN FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

X	1E	Z	15	Z	20	Z	21	0	0	0	0	Y	23	N	24	L	25	E	3	5	5	5
---	----	---	----	---	----	---	----	---	---	---	---	---	----	---	----	---	----	---	---	---	---	---

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0
---	---

 2B1 battery charger would not pick up the electrical load because the high voltage

1	1
---	---

 cut-out had actuated. The backup battery charger was connected within 2 hours as

1	2
---	---

 required by technical specification. The high voltage cut-out was reset.

1	3
---	---

 The battery charger was tested satisfactorily and returned to service. Action

1	4
---	---

 statement 3.8.2.5 was terminated at 1010 hours, August 12, 1981. (81-73)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1	5
---	---

E	28
---	----

0	8	0	29
---	---	---	----

N	A	30
---	---	----

B	31
---	----

 Routine Surveillance
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1	6
---	---

Z	33
---	----

Z	34
---	----

N	A	35
---	---	----

N	A	36
---	---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
PERSONNEL EXPOSURES
NUMBER TYPE DESCRIPTION

1	7
---	---

0	0	0	37
---	---	---	----

Z	38
---	----

N	A	39
---	---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
PERSONNEL INJURIES
NUMBER DESCRIPTION

1	8
---	---

0	0	0	40
---	---	---	----

N	A	41
---	---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION

1	9
---	---

Z	42
---	----

N	A	43
---	---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
PUBLICITY
ISSUED DESCRIPTION

2	0
---	---

N	44
---	----

N	A	45
---	---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
NAME OF PREPARER Frank Dickey
PHONE 609-935-5100
NRC USE ONLY
8109210079 810909
PDR ADOCK 05000311
PDR