

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	2	7	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	4			E
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	LICENSE TYPE JO					57	CAT	Sc

CONT

REPORT SOURCE 1 0 5 0 0 0 3 1 1 7 0 8 1 4 8 1 0 0 9 8 1 9

DOCKET NUMBER 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On August 13, 1981, the prelubricating oil pump motor on 2C diesel was removed for repair. No action statement was entered because the pump was not specified as an item which would render the diesel inoperable. At 1130 hours, August 14, 1981, 2C diesel generator was declared inoperable, and action statement 3.8.1.1.a was entered after Alco Engine Division stated that lack of prelubrication for greater than 12 hours would extend the starting time to greater than 10 seconds.

7 8 9

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 2 The motor of the prelubrication pump was rewound and reinstalled. The pump assembly  
1 1 was tested satisfactorily. Surveillance procedure SP(O)4.8.1.1.2 was satisfactorily  
1 2 performed on 2C diesel within the required starting time. At 2100 hours,  
1 3 August 15, 1981, 2C diesel was returned to service and action statement 3.8.1.1.a  
1 4 was terminated.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
1	5	E	28	0	9	0	29	N/A	30	A	31	Operator Observation	32

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 2 33 34 NA

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES			
NUMBER	TYPE	DESCRIPTION	
17	d o o (37)	2 (38)	NA

		11 12 13				
		PERSONNEL INJURIES				
NUMBER		DESCRIPTION			(41)	
1	8	0	0	0	(40)	NA

8 9		11 12		60	
LOSS OF OR DAMAGE TO FACILITY		(43)			
TYPE		DESCRIPTION			
1	9	2	(42)	NA	

2 0 N 44 NA 45 NRC USE ONLY

NRC USE ONLY

8109210182 810909  
PDR ADCK 05000311  
S PDR

AREP

Frank Dickey

PHONE

609-935-5100