

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	14						25										26					57 CAT 58					
		LICENSEE CODE						LICENSE NUMBER										LICENSE TYPE										

CON'T

REPORT SOURCE 1 6 0 5 0 0 0 2 7 2 7 0 9 0 2 8 1 8 0 9 1 4 8 1 9

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DUCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On September 2, 1981, during a routine containment inspection, an operator discovered

0 3 service water leaking from a secondary coil on No. 14 containment fan coil unit

0 4 (CFCU), at a rate of approximately 1 gallon per minute. In accordance with

0 5 NRC IE Bulletin 80-24, the NRC was notified of the service water leak in containment

0 6 by telephone, with written confirmation transmitted within the next 24 hours. No. 14

0 7 CFCU was removed from service, and declared inoperable. Action statement 3.6.2.3.a

0 8 was entered at 1935 hours, September 2, 1981.

SYSTEM CODE S B 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE H T E X C H 14				COMP SUBCODE G 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 1 21 22		SEQUENTIAL REPORT NO 0 7 6 24 26		OCCURRENCE CODE 0 1 28 29		REPORT TYPE T 30		REVISION NO 0 32									
ACTION TAKEN F 18		FUTURE ACTION A 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED Y 23		NPRO-4 FORM SUB Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER W 1 2 0 3	

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 1 The leakage was due to secondary coil failure. The leaking cooling coil was blank

1 1 flanged off and the CFCU was tested satisfactory and returned to service. Action

1 2 statement 3.6.2.3.a was terminated at 1930 hours, September 3, 1981.

1 3 (81-10, 81-11, 81-31, 81-39, 81-64, 81-72, 81-74, 81-77)

1	4											
7	8	9										

FACILITY STATUS		% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION						
1	5	E	28	0	9	2	29	N/A	B	31	Leak discovered during routine inspection

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z 33 Z 34

AMOUNT OF ACTIVITY (35)  
N/A

LOCATION OF RELEASE (36)  
N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)		(39) N/A

PERSONNEL INJURIES		DESCRIPTION (41)	
NUMBER			
1	0	0	0
2	0	0	0
3	0	0	0
4	0	0	0
5	0	0	0
6	0	0	0
7	0	0	0
8	0	0	0
9	0	0	0
10	0	0	0
11	0	0	0
12	0	0	0
13	0	0	0
14	0	0	0
15	0	0	0
16	0	0	0
17	0	0	0
18	0	0	0
19	0	0	0
20	0	0	0
21	0	0	0
22	0	0	0
23	0	0	0
24	0	0	0
25	0	0	0
26	0	0	0
27	0	0	0
28	0	0	0
29	0	0	0
30	0	0	0
31	0	0	0
32	0	0	0
33	0	0	0
34	0	0	0
35	0	0	0
36	0	0	0
37	0	0	0
38	0	0	0
39	0	0	0
40	0	0	0
41	0	0	0
42	0	0	0
43	0	0	0
44	0	0	0
45	0	0	0
46	0	0	0
47	0	0	0
48	0	0	0
49	0	0	0
50	0	0	0
51	0	0	0
52	0	0	0
53	0	0	0
54	0	0	0
55	0	0	0
56	0	0	0
57	0	0	0
58	0	0	0
59	0	0	0
60	0	0	0
61	0	0	0
62	0	0	0
63	0	0	0
64	0	0	0
65	0	0	0
66	0	0	0
67	0	0	0
68	0	0	0
69	0	0	0
70	0	0	0
71	0	0	0
72	0	0	0
73	0	0	0
74	0	0	0
75	0	0	0
76	0	0	0
77	0	0	0
78	0	0	0
79	0	0	0
80	0	0	0
81	0	0	0
82	0	0	0
83	0	0	0
84	0	0	0
85	0	0	0
86	0	0	0
87	0	0	0
88	0	0	0
89	0	0	0
90	0	0	0
91	0	0	0
92	0	0	0
93	0	0	0
94	0	0	0
95	0	0	0
96	0	0	0
97	0	0	0
98	0	0	0
99	0	0	0
100	0	0	0

7	8	9	10	11	12	N/A										80
		LOSS OF OR DAMAGE TO FACILITY		(43)												
		TYPE		DESCRIPTION												

7 8 9 10 N/A 80

PUBLICITY  
ISSUED DESCRIPTION (45) NRC USE ONLY

20		N		44		DESCRIPTION									
						N/A									

NRC USE ONLY

8109220610 810914  
PDR ADOCK 05000272  
S PDR

PARER

Frank Dickey

PHONE: 609-935-5100

000 017-978