

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

0	1	A	L	B	R	F	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	9						14	15	26										30	57					CAT	58			
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE										

CON'T

0	1
7	8

REPORT SOURCE

1	6	0	5	0	0	0	2	5	9	7	0	8	2	2	8	1	8	0	9	1	8	8	1	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

0 2 | During refueling outage, while modification of torus was in progress, fire watch was
0 3 | not posted in the immediate vicinity of welding operations. (T.S. 3.11.H) A fire
0 4 | occurred and was not extinguished as rapidly as it would have been had the fire
0 5 | watch been posted in the immediate vicinity. There was no danger to the health or
0 6 | safety of the public. Redundant systems were not applicable. Previous similar
0 7 | event: BFRO-50-259/76005W.

08		7		9		80															
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMP SUBCODE		VALVE SUBCODE													
Z	Z	A		E		Z		Z													
9	10	11	12	13	14	15	16	17	18												
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.													
8	1	0	5	2	0	3	L		0												
21	22	23	24	25	26	27	28	29	30	31											
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
H	Z	Z		Z		Z		0	0	0	0	Y		N		Z		Z	9	9	9
13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Personnel error. Re instructed all trades and labor foremen to post fire watches

1 1 per standard practice BF 14.16. The responsible personnel were given appropriate

1 2 disciplinary action.

1 3

1 4

1 6 H 30 0 0 0 29 OTHER STATUS 30 31 A 32 NRC inspector observed 33 Z 34 35 NA 36 NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
000	Z	NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	2	3	4
0	0	0	(41) NA

		LOSS OF OR DAMAGE TO FACILITY		(4)
		DATE		DESCRIPTION
1	2	3	4	
				NA

PUBLICITY
 POSTED DESCRIPTION (45)
 (2) (3) (N) (44) NA

NRC USE ONLY

6109240308 810918
PDR ADCK 05000259
S PDR

Gene Holder

PHONE (205) 729-6134

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 81052 Technical Specification Involved 3.11.H
Reported Under Technical Specification 6.7.2.b(3) *Date due NRC: 9/21/81
Date of Occurrence 8/22/81 Time of Occurrence 0320 Unit 1

Identification and Description of Occurrence:

Fire watch was not posted in the immediate vicinity of welding operations.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 in routine startup.

Unit 3 in routine startup.

Action specified in the Technical Specification Surveillance Requirements met
due to inoperable equipment. Describe

None

Apparent Cause of Occurrence:

Personnel error.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Reinstructed all trades and labor foremen to post fire watches per standard practice BF 14.16. The responsible personnel were given appropriate disciplinary action.

Failure Data: BFRO-50-259-76005W.

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: *ALL*