

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 N Y I P S 2 2 0 0 - 0 0 0 0 0 - d 0 3 4 1 1 1 1 1 4 5

REPORT SOURCE L 6 0 5 0 0 0 2 4 7 7 0 4 2 1 8 3 8 0 5 2 1 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

2 During normal operation No. 21 Charging Pump developed a leak and was declared inoperable
3 (T.S.3.2.C.1). At the time No. 23 Charging Pump was out of service while redundant
4 pump No. 22 was operable. Pump No. 21 was returned to service within the allowed time
5 period. The health and safety of the public were unaffected. Previous similar events:
6 LER 75-25, 75-27, 82-24, 82-34.

SYSTEM CODE P C 11 CAUSE CODE F 12 CAUSE SUBCODE B 13 COMPONENT CODE P U M P X X 14 COMP. SUBCODE E 15 VALVE SUBCODE Z 16

LER/RO REPORT NUMBER 8 3 EVENT YEAR 8 3 SEQUENTIAL REPORT NO. 0 1 4 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0

ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER U 0 5 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

0 The cause of the leak was determined to be a defective head gasket on No. 4 cylinder
1 head. The gasket was replaced and the pump was returned to service. Pump Data:
2 Union Pump Co. Model OX-300 Quintuplex variable speed positive displacement pump.

FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY Operator Observation 31 DISCOVERY DESCRIPTION 32

ACTIVITY RELEASED Z 33 CONTENT OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE 38 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PURBICITY ISSUED N 44 DESCRIPTION NA 45

8306170044 830521
PDR ADOCK 05000247
S PDR

NRC USE ONLY

Gary Hinrichs

PHONE: (914) 526-5543

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

May 21, 1983

Re: Indian Point Unit No. 2
Docket No. 50-247
LER-83-014/03L-0


Mr. James M. Allan,
Acting Regional Administrator-Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. Allan:

The attached Licensee Event Report LER-83-014/03L-0 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.7. This event is of the type described in Technical Specification 6.9.1.7.2.b.

Three copies of this letter and attachment are enclosed as required.

Very truly yours,



attach.

cc: Mr. Richard DeYoung, Director (30 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. William G. McDonald, Director (3 copies)
Office of Management Information and Program Control
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Thomas Foley, Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

IE22
11