

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 WIKNP1200-00000-0034111145

LICENSEE CODE

LICENSE NUMBER

LICENSE TYPE

CAT 58

CON'T

01 L05000305706038380701839

REPORT SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During full power operation, while performing the monthly RHR pump and valve  
03 surveillance test, containment sump B isolation valve SI-350B would not cycle closed.  
04 This required the valve to be taken out of service to perform corrective maintenance.  
05 This placed the plant in an LCO per T.S.3.3.a.2.D and is reportable per T.S.6.9.2.b.(2).  
06 Since the redundant train was available to function during accident conditions, there  
07 was no effect on the health and safety of the public.

08

09 SF11 E12 B13 CKTBRK14 X15 Z16

SYSTEM CODE

CAUSE CODE

CAUSE SUBCODE

COMPONENT CODE

COMP. SUBCODE

VALVE SUBCODE

LER/RO REPORT NUMBER

EVENT YEAR

SEQUENTIAL REPORT NO.

OCCURRENCE CODE

REPORT TYPE

REVISION NO.

ACTION TAKEN

FUTURE ACTION

EFFECT ON PLANT

SHUTDOWN METHOD

HOURS

ATTACHMENT SUBMITTED

NPRD-4 FORM SUB.

PRIME COMP. SUPPLIER

COMPONENT MANUFACTURER

E18 Z19 Z20 Z21 0000 N23 Y24 N25 W120

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Valve SI-350B failed to cycle closed because the mechanical interlock on the breaker  
11 was sticking in the open position. The mechanical arm was exercised, the valve cycled  
12 and returned to operation within T.S. time limits. The surveillance test was then  
13 completed satisfactorily. No further action is required.

14

15 E28 10029 NA B31 RHR Pump and Valve Surveillance Test

FACILITY STATUS

% POWER

OTHER STATUS

METHOD OF DISCOVERY

DISCOVERY DESCRIPTION

ACTIVITY CONTENT

RELEASED OF RELEASE

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

16 Z33 Z34 NA NA

PERSONNEL EXPOSURES

NUMBER

TYPE

DESCRIPTION

17 00037 Z38 NA

PERSONNEL INJURIES

NUMBER

DESCRIPTION

18 00040 NA

LOSS OF OR DAMAGE TO FACILITY

TYPE

DESCRIPTION

19 Z42 NA

PUBLICITY

ISSUED

DESCRIPTION

8307110284 830701  
PDR ADOCK 05000305  
S PDR

NRC USE ONLY

20 N44 NA

NAME OF PREPARER S. L. Bernhoft/J. G. Thorgersen

PHONE: (414) 388-2560

CPO 917-926

## WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

July 1, 1983

Mr. J. G. Keppler, Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305  
Operating License DPR-43  
Reportable Occurrence 83-014/03L-0

In accordance with the requirements of the Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence 83-014/03L-0 is being submitted.

Very truly yours,

A handwritten signature in cursive script, appearing to read "C. W. Giesler".

C. W. Giesler  
Vice President - Nuclear Power

js

Attach.

cc - Dir, Office of Inspection & Enforcement  
US NRC, Washington, DC 20555  
Dir, Office of Mgt Info & Program Control  
US NRC, Washington, DC 20555  
INPO Records Center  
Suite 1500, 1100 Circle 75 Parkway  
Atlanta, GA 30339  
Mr. Robert Nelson, NRC Resident Inspector  
RR #1, Box 999, Kewaunee, WI 54216  
Mr. S. A. Varga, Chief  
US NRC, Washington, DC 20555

IEJ 1/1  
JUL 6 1983