

CONTROL BLOCK:

--	--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE 09		CAUSE CODE HH 11		CAUSE SUBCODE E 12		COMPONENT CODE VALVOP 14				COMP SUBCODE B 15		VALVE SUBCODE Z 16	
LER/O REPORT NUMBER 17		EVENT YEAR 83 21 22		SEQUENTIAL REPORT NO. 004 24 26		OCCURRENCE CODE / 27		REPORT TYPE L 29		REVISION NO. 0 32			
ACTION TAKEN B 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0000 22		ATTACHMENT SUBMITTED N 23		NPRO-4 FORM SUB N 24	
PRIME COMP SUPPLIER L 25		COMPONENT MANUFACTURER 1200 26											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

NAME OF PREPARER Z. E. Berry PHONE (305) 245-2910 Ext. 353

USNRC REGION II
ATLANTA, GEORGIA

83 JUN 30 AIO: 07



June 23, 1983
PNS-LI-83-434-1

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-83-04

TURKEY POINT UNIT 4

DATE OF OCCURRENCE: MAY 25, 1983

TECHNICAL SPECIFICATION 6.9.2.b.2

AUXILIARY FEEDWATER PUMP

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. W. Williams, Jr.", is written over the typed name.

J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

OFFICIAL COPY

IE 22 11

PEOPLE...SERVING PEOPLE