



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BAYTOWN, TEXAS 77524


AREA CODE 713 6631

July 26, 1983

RBG- 15,531

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-114

On April 19, 1983, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning weld defects in the radial rebar anchor ring for the Shield Building Roof (DR-114). GSU is awaiting results of additional inspections from our architect-engineer. An interim or final status report will be provided by September 19, 1983.

Sincerely,

William J. Booker
for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

PJD
JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

P. L. Brown (SRI)

8308030243 830726
PDR ADOCK 05000438
S PDR

IE-27
110