

## EXPIRES 4-30-82

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE: (704) 373-7432

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

July 27, 1983

USNRC REGION II  
ATLANTA, GEORGIA

TELEPHONE  
(704) 373-4531

83 AUG 3 A10:12

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street NW, Suite 2900  
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Unit 1  
Docket No. 50-369  
LER/RO-369/83-49

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/83-49. This report concerns T.S. 3.3.2, "The engineered safety features actuation system instrumentation channels and interlocks shown in Table 3.3-3 shall be operable... with response times as shown in Table 3.3-5". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

*H.B. Tucker*

Hal B. Tucker

PBN:jfw  
Attachment

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

Mr. W. T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

OFFICIAL COPY

1522

1/1