

CONTROL BLOCK: [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

03

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9

ACTIVITY	CONTENT					
			(16)		(16)	

PERSONNEL EXPOSURES 19PERSONNEL INJURIES
NUMBER OF PERSONNEL INJURIES (41)

LOSS OF OR DAMAGE TO FACILITY (43)

PUBLICITY (45) NRC USE ONLY

NAME OF PREPARED: Lamar McLaughlin PHONE: (305) 465-3550 x3574

USNRC REGION II
ATLANTA, GEORGIA



83 AUG 31 P 1: 58

August 29, 1983
PNS-LI-83-576-1

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 50-389-83-42

ST. LUCIE UNIT 2

DATE OF OCCURRENCE: AUGUST 1, 1983

TECHNICAL SPECIFICATION 3.3.4

C TURBINE INTERCEPT VALVE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. W. Williams, Jr.", is written over the typed name.

J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PLP/mpc

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 SL

OFFICIAL COPY
1822
1/1

PEOPLE...SERVING PEOPLE